B.R. No: 444/14-15, Date: 31/7/2014

Inspection report for the work of : Improvements to road from Babanna layout Market area to Shettyhalli, in Ward no. 12, in Shettyhalli Sub-Division

By

Sri. *G.M. Muniyappa*

Inspection Report

Name of Work	:	Improvements to road from Babanna layout Market area to Shettyhalli, in Ward no. 12, in Shettyhalli Sub-Division
Work Order	:	No. EE/DD/WO/88/13-14, Dated: 27/06/2014
Agency	:	KRIDL
B.R. No & Dated	:	444/14-15, Date: 31/7/2014
Bill Amount	:	Rs. 49.50 lakhs.
Job Code	:	012-14-000032
P. Code	:	P-2654

Date of Inspection — 05-09-14

The above said Work Improvements to road from Babanna layout Market area to Shettihalli in Ward (12) in Shettihalli has been shown by the Concerned AE

The above said Work has been inspected along with Concerned AE the Length of the Asphalted Road and Width of the Carriage width of the Road of the entire length of the Road has been checked by me and it is found Satisfactory

the Trial pits of the Asphalted Road has been opened by me and depth of the Bituminous layer at different locations has been checked by me and it is found Satisfactory

54

Asst. N.K. — ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು G.M.MUNIYAPPA 05/09/14

ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ B.E.(ELECT),B.E.,(CIVIL)
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ EXECUTIVE ENGINEER(S/D)
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು. PUBLIC WORKS DEPARTMENT

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂ